



Pair Twin Disc 514C Marine Gears - Ratio 4.5:1

PRODUCT DESCRIPTION

Good RTO units

One unit - had a drip leak from above the warehouse and caused some surface rust in the gear teeth.. See picture.. Do not see any chipped teeth..

Second unit - clean

SAE #1 Bellhousing

Came out running from the vessel.

Categories: [Marine Gears](#)

Gear Manufacturer Twin Disc

Gear Model 514C

Gears Output Straight

Gear Condition Running Take Out - RTO

Ratio 4.5

Condition RTO



