



Single Cummins KTA19 - 600HP - needs rebuild

PRODUCT DESCRIPTION

Approximately 14,000 hours. Number 5 cylinder was damaged, this engine will need to be rebuilt. All the parts are not in these pictures, but the engine is complete including a new flywheel, vibration damper, etc. No starter and no alternator.

Categories: [Marine Engines](#)

Engine Manufacturer/Brand Cummins

Engine Model KTA19

HP 600

RPM 1800

Hours on Equipment 14,000



