



Yanmar 4LHA-STP 240HP-bobtail-rebuilt

PRODUCT DESCRIPTION

pigtail harness included, but no panel bobtail. Came out of a pleasure craft. It had 720hrs on it before owner spun a main bearing (at idle speed) due to a disconnected oil line. The motor was then completely torn down, inspected and all tolerances checked. All new piston rings and bearings were installed after the crankshaft and cylinders were honed and/or polished plus a brand new Turbo. New liners were put in for the cylinders and we rebuilt the cylinder head. Rebuilder does not transfer warranty, so no warranty.

Categories: [Marine Engines](#)

Engine Model 4LHA-STP

HP 240

Condition Rebuilt

Coming soon!

