



---

## CAT 3208T 435hp - 8500 hours

---

### PRODUCT DESCRIPTION

It smokes more than it should that's about all owner knows. He hasn't had any tests done recently. He got tired of the oil in the bilge and the smoke. Puff black smoke when you gun up onto a plane then it's gone. Fuel pump leaks on top the motor a little. Owner had it rebuilt last year and it was shipped. UPS is going to cover the pump repair bc they bent the housing end in shipping. Sold As Is currently - If he has to take it to mechanic for fixing the pump then a little more.

**Categories:** [Marine Engines](#)

**Cooling Method** Heat Exchanger

**Engine Manufacturer/Brand** CAT

**Engine Model** 3208

**HP** 435

**Condition** RTO

**Additional Information** Have a video of it pushing owners boat pretty good right before he took it out.

---



