



Cincinnati 1010 Hydraulic Shear

PRODUCT DESCRIPTION

Meets safety standards No. 38904

Last used around 2020

Blade is reported to be clean and the hydraulic reported to be good. It most likely needs some cleaning and minor repair.

Used for about 15 years for roofing trim.

It is stored approximately 40ft from a 3 ph electric outlet. You are welcome to bring an electrician to power it up.

Categories: [Auxiliary Engines](#)

