



Incomplete Rebuild 3208 375HP

PRODUCT DESCRIPTION

Unable to finish partial rebuild 3208 w 375HP. Needs Injectors, turbo, and water pump. New pistons, cams, gears, and heads sent out.

Categories: Marine Engines

Condition Rebuilt

Coming soon!

