



Single MAN 2840 LE 403 Marine Engine - Needs top end rebuild - Hours 2533

PRODUCT DESCRIPTION

Year 2000 One motor went bad Blown turbo from really lack of use, Found little bit of precipitation in the cylinders. the mechanic scoped the cylinders and saw some rust. needs the top end redone. one cracked sleeve. Turbo went out and went through the intercooler. had 2100 hours before turbo messed up.

Has a 2005 model black boxes. sold separately. Tags are on both motors Has oil samples as well.

Categories: [Marine Engines](#)

Cooling Method Heat Exchanger

Engine Manufacturer/Brand MAN

Engine Model 2840 LE 403

HP 1050

RPM 1050

Condition RTO

Additional Information Boxed up ready to go..



