



ZF Hurth TRANSMISSION 63 2:1- Rebuilt

Coming soon!

PRODUCT DESCRIPTION

ZF HURTH TRANSMISSION THAT WAS JUST REBUILT. HSW 630V1-2,OR A=2.00 B=2.03 CAME OFF A YANMAR 6LP STE . BOTH CLUTCH PLATES ARE BRAND NEW HURTH PLATES. IT WAS TESTED AND SOLID WARRANY FOR 90 DAYS . BRAND NEW VALVE

Categories: <u>Marine Gears</u> Gear Condition Rebuilt Condition Rebuilt

