



---

## ZF Hurth TRANSMISSION 63 2:1- Rebuilt

---

### PRODUCT DESCRIPTION

ZF HURTH TRANSMISSION THAT WAS JUST REBUILT.  
HSW 630V1-2,OR A=2.00 B=2.03 CAME OFF A YANMAR  
6LP STE . BOTH CLUTCH PLATES ARE BRAND NEW  
HURTH PLATES. IT WAS TESTED AND SOLID WARRANY  
FOR 90 DAYS . BRAND NEW VALVE

**Categories:** [Marine Gears](#)

**Gear Condition** Rebuilt

**Condition** Rebuilt

---

