



(2) VOLVO TAMD 60 C Marine Engines

PRODUCT DESCRIPTION

Engines are outside but tarped with a metal cap.

Used for fishing and diving.

Raw water cooling.

Hull cooling.

He would go through the engines before putting in a boat.

They were running when taken out about 4 years ago.

Stored inside for 2.5 years. Been sitting out for a year and half.

The last rebuilt was about 10 years ago

(1) Starter has lug broken, occurred on the takeout.



Categories: [Marine Engines](#)

Cooling Method Keel Cooled

Engine Manufacturer/Brand Volvo

Engine Model TAMD 60c

HP 250

Hours on Equipment 1500

Condition Rebuilt

