



42 Ft Aluminum Crewboat

PRODUCT DESCRIPTION

42' ALUMINUM CREW BOAT

- COAST GUARD INSPECTED AND DOCUMENTED FOR LAKES, BAYS AND
- SOUNDS - COI IS BEING DROPPED ON THIS VESSEL
- CUMMINS ELECTRONIC CONTROLLED 400 HP TIER 3 COMPLIANT
- 6KW NORTHERN LIGHTS GENERATOR
- GARMIN RADAR
- GARMIN CHART PLOTTER AND SOUNDER
- FRESH AND SALT WATER WASHDOWN
- CRUISES AT 22 KTS
- INSPECTED FOR 14 PASSENGERS WITH 2 CREW MEMBERS (when COI active)

Categories: [Crew Boats](#)

Engine Manufacturer/Brand Cummins

Engine Model QSL9

HP 400

Hours on Equipment 9300

Condition Used

Additional Information


Owner ran this boat all through the winter of 2021-2022 in the Bay in all types of conditions. Last February during an inspection, the CG identified two cracked welds in the framing. Instead of welding them up and/or installing an extra bracing, this led to a can of worms - they wanted a complete Marine Survey and all kinds of reinforcements installed in the boat which would require removing the interior cabin etc.

It has been sitting for a year and the owner recently made the decision to sell instead of using funds to complete the required "repairs".

 **COMMERCIAL**
— MARINE PRO —



They have tried to secure work as a 6 pack boat – but their business just requires inspected vessels. It is their opinion that there is nothing wrong with the seaworthiness of this vessel - they just drew an over the top inspector plus they didn't have their Port Captain at the inspection to make intelligent arguments – they had a guy on it that had never been in charge of an inspection before.

 **COMMERCIAL**
— MARINE PRO —