



Cummins 6BTA 330HP Rebuilt

PRODUCT DESCRIPTION

Zero Hour Full Rebuild

API parts

In House rebuild

CPL 1975

Categories: Marine Gears

Cooling Method Heat Exchanger

Engine Manufacturer/Brand Cummins

Engine Model 6Bta

HP 330

RPM 2800

Condition Rebuilt













