



Marine Transmission HSW630A1 - new plates rebuilt

PRODUCT DESCRIPTION

ZF Hurth Transmission - New clutch plates - rebuilt - all gears in top shape - state of pump unknown, may need replacing. came out of 46' Bayliner. 2-1 RATIO

Categories: <u>Marine Gears</u> Condition Rebuilt









