



---

## Pair 3208 210HP w Twin Disc 506 2:1

---

### PRODUCT DESCRIPTION

One of them is perfectly functional and runs like a dream. The other one is out of time (no compression), and the transmission needs work/replacing. Hours cannot be verified, but they are currently installed and is said to be in great shape.

**Categories:** [Marine Engines](#)

**Engine Manufacturer/Brand** CAT

**Engine Model** 3208

**HP** 210

**Condition** RTO

