



Pair 6BT 210HP - Rebuilt - running video

PRODUCT DESCRIPTION

Fresh rebuilds. Total rebuild.
Everything is new except the water pump and alternator.
Need to blast the raw water cooling pipe and paint.
All parts were bought off diesel pros, not cummins.
Injectors and pumps were professionally rebuilt.
Also available Twin Disc 506 2:1 gears.
Needs to be painted.

<https://youtube.com/shorts/tMNzkHg3qml?feature=share>

https://youtu.be/X-AE_p0IV-k



Categories: [Marine Engines](#), [Marine Gears](#)

Engine Manufacturer/Brand Cummins

Engine Model 6BT

HP 208

Gear Manufacturer Twin Disc

Gear Model 506

Gears Output Straight

Gear Condition Rebuilt

Ratio 2:1

Condition Rebuilt



