



Pair CAT 3208 375HP - bobtail

PRODUCT DESCRIPTION

Do not have panels nor harnesses. They have 1500 hours on them. No videos. They were removed from a pleasure boat because of the oil consumption. Engines are definitely not leaking oil, but would need some attention given to them before dropping them into anything. Price is for the pair.

Categories: [Marine Engines](#)

Engine Manufacturer/Brand CAT

Engine Model 3208

HP 375

Condition RTO

