



---

# Pair Cummings QSM11 Marine Propulsion Engines 715HP

---

## PRODUCT DESCRIPTION

Running take outs - maintained throughout ownership.

Being pulled for repower.

Approximately 10,000 hours. When boat was purchased it has 1,200 original hours. Cracked head in one last year, the head was replaced. All cylinders were scoped when a single hairline crack was found. Injectors in both were placed in Jan/Feb 2024.

ZF 325-1A gears 1.485:1 Ratio

Being pulled from a 46' fisherman Fall of 2024

**Categories:** [Marine Engines](#)

**Engine Manufacturer/Brand** Cummins

**Engine Model** QSM11

**HP** 715

**Hours on Equipment** 10,000

**Additional Information** Video of panel read out while in use: [IMG\\_0](#)

---



