



Single MAN 2840 LE 403 Marine Engine

PRODUCT DESCRIPTION

1050HP Marine Engines. It needs to be overhauled due to cylinder wear. Approx 5k hours. The manifolds, heat exchanger assembly, and the aftercooler core have been removed. Due to the liners being rusted, it does not bar over. Engine has been stored in an open air storage facility.

Categories: [Marine Engines](#)

Cooling Method Heat Exchanger

Engine Manufacturer/Brand MAN

Engine Model 2840 LE 403

HP 1050

Condition RTO

