



Pair Volvo TAMD 103A 400HP

PRODUCT DESCRIPTION

One engine has bad crank
all heads were rebuilt on one unit.
Other engine is running take out
still in the boat
purchased new in 2005 used in season business

Categories: [Marine Engines](#)

Engine Model TAMD 103A

Coming soon!