



Pair Yanmar 4BY3 150 Marine Propulsion Engines

PRODUCT DESCRIPTION

2014

1 engine running perfectly with low hours 1 engine has cracked head cover - cylinder head #120650-11510 and also missing the turbo charger included throttle controls and lots spare parts, including held held testing computer Bobtail

Hour meter reads 2300 hours.

Pulled October 2023. Running when pulled. Replacing with new.

Categories: Marine Engines

Engine Manufacturer/Brand Yanmar

Engine Model 4BY3

HP 150

Additional Information Video: [video width="176"

height="144"

mp4="https://commercialmarinepro.com/wp-content/up loads/2023/12/20230916_151340_001-1.mp4"][/video]













