



# Pair ZF Marine Gears 350-1 2.077 to 1 ratio

## PRODUCT DESCRIPTION

They reported around 6000 hours. They came out of a yacht refit.

One Transmission is missing the oil pressure sender

Everything else looks fine.

**Categories:** [Marine Gears](#)

**Gear Manufacturer** ZF

**Gear Model** IRM350PL

**Ratio** 2.077

