



## Single Detroit 271 20kw Genset

## **PRODUCT DESCRIPTION**

The was replaced because the other kept blowing head gaskets. It ran great for 6 months after the head was replaced.

The unit was running when pulled. Hours not known.

**Categories:** Marine Generators

**Generator Manufacturer/Brand** Detroit

kW Rating 20





