



×

Single/Pair 7261 3.84:1

PRODUCT DESCRIPTION

Good Running Take out. Came off the back of CAT D399 engines, ships they came off was standby vessel in the oil industry so well maintained, ships were laid up for about 1 year before we got them for braking so about 2 1/2 years, always been in the dry under cover

Categories: Marine Gears

Condition RTO

