
Twin Disc 507 2:1 straight output



PRODUCT DESCRIPTION

Was attached to a 6CTA w 450HP. Purchased as part of a boat. Ran the boat 10hrs for stransfer without any issues, then pulled everything. Replaced rear seal, which was leaking. Boat pulled from did not have a working hour meter. Sold As-Is.

Categories: Marine Engines
Engine Model 6CTA
HP 450
Condition RTO

