



---

## Twin Disc 507 2:1 straight output

---

### PRODUCT DESCRIPTION

Was attached to a 6CTA w 450HP. Purchased as part of a boat. Ran the boat 10hrs for transfer without any issues, then pulled everything. Replaced rear seal, which was leaking. Boat pulled from did not have a working hour meter. Sold As-Is.

Categories: [Marine Engines](#)

Engine Model 6CTA

HP 450

Condition RTO

