



Twin Disc 540 Marine Gear - 6:1 Ratio - Broken bellhousing and output teeth

PRODUCT DESCRIPTION

Good RTO - Gears inside in great condition. When gear was being removed for smaller gear, they hit the bellhousing and broke part of it and a few teeth on external spider gear.

Categories: [Marine Gears](#)

Condition RTO

