Volvo 71a 375HP



PRODUCT DESCRIPTION


Engine is 1988 with apx. 2300 hours. Engine ran great when pulled. The heat exchanger after cooler and gear cooler just serviced and cleaned in an ultra sonic cleaner. Has two gauge panels and harness 1 1/2 strainer and other parts that were taken out with the repower Has 2 aftercooler bundles. The housing in one of the after cooler bundles froze up over the winter and cracked. (Just one of the 4 bundles.) When pulled in 2018 was in good running condition when came out. Video is from before it was pulled.

The heat exchanger bundles were sold. Engine is not complete. The engine is turned over periodically. Stored indoors.

Categories: Marine Engines







COMMERCIAL MARINE PRO