



ZF 2050 Marine Gear - Ratio 2.029:1 - RTO

PRODUCT DESCRIPTION

Good Running Take out gear

Approx 18,000 hours on the gear.

Owner repowered the vessel with New engine and therefore purchased New Gear as well.

Clutch packs put in new in 2016

Cooler installed in 2021

Missing the gear oil cooler.



Categories: Marine Gears
Gear Manufacturer ZF
Gear Model 2050
Gears Output Straight

Gear Condition Running Take Out - RTO

Ratio 2.029:1 Condition RTO











